


Group D: Request 3.37



[Answer from NIRS]

Seven of the most internally contaminated TEPCO workers underwent a medical examination in NIRS. There were no symptoms suggesting lung injuries nor abnormalities on chest auscultation.